∞	7	6	5	4	ဒ	2	_	
94669748A	13232308	13232305	20772301 - Production 19130591 - Service	25805685 / 20772570	15020478	25825339 / 25825338	20772560	GM P/N
A07WV	1606	1603	8702E - Production 8704 - Service	8645R 8645E 8700R 8700E	7803E	3454E / 3455E	8703E	Sanden P/N
DM 90040	N1AW10	N1KFU	08J70-010 GM-37278	08J70-00R 0PH60-003 08J70-00Z 0PH60-004	GM-41863 (JPY) GM-37278 (USD)	GM-41863	GM-41863 (JPY) GM-37278 (USD)	Contract #
\$ 1,932.16	\$ 1,050.00 paid	\$ 473.23	\$ 159,013.68	pri be \$ 800,000.00 of	Cur incc \$ 23,961.28 cod	\$ 27,349.13	Curre incon \$ 24,256.19 code	Approximate Dispute Amount
are not sure why - all parts were 1,932.16 delivered by Sanden	Sample part - delivered but not paid	Sample part - delivered but not paid PO was setup in Euro - Sanden remit was to be USD only (No Euro 473.23 currency setup)	9 8	restment amortized in piece ce is estimate - final number to calculated by either projection future volumes or final number	Currency Discrepancy - Contract the parts into their system - incorrectly setup with wrong source Evidence of receipt from GM existing	27,349.13 Price Discrepancy	Currency Discrepancy - Contract Filed claim with incorrectly setup with wrong source disbursements code Claim #167480	Issue
			GM to provide details on how to proceed with filing obsolesce and agree to cover the remaining volume	Need EOL volumes and agreement to the MOU lump sum payment condition to be carried over	GM has yet to correctly receive the parts into their system - Evidence of receipt from GM existing	Submitted evidence prior to C11 filing yet still unresolved	Filed claim with GM disbursements Claim #16748068	Current Status

